


$\frac{1}{12}$

Fig. 1 PRIOR ART



$\frac{2}{12}$

Fig. 2A




Fig. 2B




Fig. 2C




Fig. 2D




Fig. 2E




Fig. 2F




Fig. 3





Fig. 4

$\frac{4}{12}$

Fig. 5A




Fig. 5B




Fig. 5C




Fig. 5D




Fig. 5E




Fig. 5F





Fig. 5G



$\frac{5}{12}$

Fig. 5H




Fig. 5I




Fig. 5J




Fig. 5K




Fig. 5L




Fig. 5M





Fig. 5N



$\frac{6}{12}$

Fig. 6




Fig. 7






Fig. 8



$\frac{8}{12}$

Fig. 9



$\frac{9}{12}$

Fig. 10A




Fig. 10B




Fig. 10C




Fig. 10D




Fig. 11





Fig. 12






Fig. 13A

—→ INCREASING GROOVE WIDTH

—→ INCREASING GROOVE DEPTH

Fig. 13B